National Transportation Safety Board NTSB ID: IAD02LA021 Aircraft Registration Number: N207TA FACTUAL REPORT Occurrence Date: 12/20/2001 Most Critical Injury: None AVIATION Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone ME 04210 2000 EST Lewiston Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Cessna 208B Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On December 20, 2001, about 2000 eastern standard time, a Cessna 208B, N207TA, was substantially damaged during an aborted takeoff from the Auburn/Lewiston Municipal Airport (LEW), Lewiston, Maine. Teleford Aviation, Inc., doing business as United Parcel Service, operated the airplane. The certificated commercial pilot was not injured. Instrument meteorological conditions existed at the time, for the flight destined for Manchester Airport (MHT), Manchester, New Hampshire. An instrument flight rules flight plan was filed for the cargo flight, conducted under 14 CFR Part 135.

According to the pilot, she arrived at the airport at 1915, and performed a preflight inspection of the airplane. Between 1928 and 1935, she loaded the airplane with cargo, then proceeded to remove snow from it by using a ladder and broom. The airplane was re-examined, and found free of any additional contamination. At 1955, the airplane taxied to the run-up area for a before takeoff check. All operational checks were normal and in accordance with limitations. At 1958, the pilot obtained her departure clearance, and was released for departure at 2000. At that time a second contamination check was conducted before she taxied slowly onto the runway due to unplowed conditions.

Once on the runway, the pilot back-taxied the full length of runway 04 and used a 10-degree flap setting for departure. The brakes were held, and the throttle was advanced to maximum takeoff limits for final checks. The pilot began the takeoff roll and rotated the airplane when it reached 90 knots. The main wheels lifted off momentarily, then settled back onto the runway.

The takeoff was aborted, the power lever was placed in the Beta/Reverse range, and the brakes were applied. The airplane slowed, but continued its slide down the center of the runway. The pilot secured the engine before the airplane overran the departure end of the runway. Once off the runway, right rudder was applied to avoid the localizer antenna. The airplane veered to the right and the left main tire caught anchor cables attached to the antenna. The airplane pivoted to the left, around the backside of the antenna, and came to rest.

During a subsequent telephone interview, the pilot added that snow had fallen throughout the preflight inspection, loading, taxi, and takeoff. After she cleaned the snow from the airplane, the surfaces were clear, but remained wet as the snow continued to fall. Before takeoff, the procedure she used was to visually check the leading edges, the cowl, the windscreen, and the struts, which were all clear of contamination. The second contamination check was performed from the cockpit, just prior to taking the runway. Both the preflight and the before-takeoff checks were completed per the Cessna manual.

There was about three-quarters of an inch of snow on the runway, and the company operations manual allowed an inch. When the pilot was asked if the runway had been plowed at any time prior to her departure, she answered that it had not been, and that, in fact, it was done after she went back to the terminal. According to the Auburn Fire Department, the runway had not been plowed when they

National Transportation Safety Board FACTUAL REPORT

NTSB ID: IAD02LA021

Occurrence Date: 12/20/2001

Occurrence Type: Accident

Narrative (Continued)

arrived on scene at 2018.

The pilot stated that she had flown for Teleford Aviation for about 1 year, and that this was her second winter season with the company. She recently completed a winter operations class and had received information from Cessna on the Caravan, as well as additional winter operations knowledge.

The pilot held a commercial pilot certificate with ratings for airplane single engine land, multi-engine land, and instrument airplane. Her most recent second-class medical certificate was issued February 5, 2001. The pilot reported that she had about 1,700 hours of flight experience, 700 hours of which were in the Caravan.

The pilot reported there were no mechanical anomalies with the airplane.

The weather reported at the airport at the time of the accident included a broken ceiling at 100 feet with an overcast layer at 800 feet. Visibility was $1 \ 3/4$ miles in light snow. The winds were from 360 degrees at 4 knots.

According to a meteorologist in the Auburn/Lewiston area, 5 inches of snow fell between 1400 on December 20, 2001, and 0700 on December 21, 2001. There was no weather observer at the Lewiston Airport to augment the AWOS system, and snow depth measurements were not available.

According to the Cessna Caravan Cold-Weather Operations Manual:

"No attempt should be made to take off with a load of ice or snow. Ice and snow on the wings will change the shape of the airfoil and disturb the flow of air over the wings, reducing available lift and airspeeds. Do not assume that light snow will melt or blow off during taxi-out or the takeoff run. Even if it does, it may reveal ice or frost beneath."

A review of the company operations manual by Teleford Aviation and the FAA after the accident resulted in new, more stringent de-ice requirements for the flight crews. Included in the new de-icing procedures was the mandatory use of de-icing fluid prior to taxi in freezing precipitation between plus 2 and minus 4 degrees Celsius.

Takeoff performance planning, as well as aborted takeoff criteria considerations for operation on contaminated runways were also added.

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: IAD02LA021

Occurrence Date: 12/20/2001

TACIDAL REFORT			72/20/2001												
AVIATION				Occurrence Type: Accident											
Landing Facility/Approach In	forma	tion													
Airport Name Air					D:	Airport Eleva	ition	Run	ınway Used Runw		way Length		Run	way Width	
Auburn Lewiston Municipal Airp				LEW		288 Ft	. MSL	. 04	4 5001		1		100)	
Runway Surface Type: Asphalt															
Runway Surface Condition: Snow-	wet														
Type Instrument Approach: NONE	Ē														
VFR Approach/Landing: None															
Aircraft Information															
Aircraft Manufacturer						Series						l Number			
Cessna				20	08B						0371				
Airworthiness Certificate(s): Norm	al														
Landing Gear Type: Tricycle															
Homebuilt Aircraft? No	Numb	er of Seats: 2	2	Cert	Certified Max Gross Wt.					8950 LBS Numb			per of Engines: 1		
• • • • • • • • • • • • • • • • • • • •				_	Engine Manufacturer: Pratt & Whitney				Model/Series: PT6A-114A			Rated Power: 675 HP			
- Aircraft Inspection Information															
Type of Last Inspection				Date of	Date of Last Inspection Time S				Since Last Inspection			Airfra	me To	otal Time	
AAIP				11/05/	11/05/2001			80.4 Hours				52	34.5 Hours		
- Emergency Locator Transmitter (ELT) In	nformation													
ELT Installed? Yes		ELT Operate	ed? No				EL	Γ Aided i	n Locating Ad	ccident S	Site? No)			
Owner/Operator Information															
Registered Aircraft Owner				Stre	Street Address 189 Odlin Road										
Teleford Aviation Inc					City							Sta	te	Zip Code	
					Bangor ME 04401									04401	
Operator of Aircraft				Stree	Street Address Same as Reg'd Aircraft Owner										
Same as Reg'd Aircraft Owner					City							Sta	te	Zip Code	
Operator Does Business As: UPS					Operator Designator Code:										
- Type of U.S. Certificate(s) Held:															
Air Carrier Operating Certificate(s):	: On-de	emand Air T	axi												
Operating Certificate:						Operator (Certifi	cate:							
Regulation Flight Conducted Under	r: Part	135: Air Ta	xi & Co	ommute	r										
Type of Flight Operation Conducted	d:														

FACTUAL REPORT - AVIATION

Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: IAD02LA021

Occurrence Date: 12/20/2001

AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name					City			State Da		Date of Birth	Age	
On File	On File			On	File	On File	31					
Sex: F Seat Occupied:		Certificate Number: On File										
Certificate(s): Fligh	Commercia	al										
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): Airpla	Instrument Rating(s): Airplane											
Instructor Rating(s): Airplane Single-engine; Instrument Airplane												
Type Rating/Endorsement fo	r Accident/In	cident Aircra	ft? Yes		(Current Bie	nnial Flight	Reviev	v? 11/0	08/2001		
Medical Cert.: Class 2	Medica	l Cert. Status	s: Valid Med	dicalw/ wa	ivers/lim.		Date of L	_ast Me	edical E	xam: 02/05/20	01	
							-					
- Flight Time Matrix All A/C This Make and Model s			Airplane Single Engine	Airplane Mult-Engine	Night	Ins Actual	trument Simulated	ı	Rotorcraft	Glider	Lighter Than Air	
Total Time	2029	749	1954	75	658	11	0	55				
Pilot In Command(PIC)	1950	749		70	655	11	0	48				
Instructor	1105	2	1105									
Last 90 Days	126	126	126		71			_				
Last 30 Days Last 24 Hours	67 2	67 2	67 2		11							
Seatbelt Used? Yes		Ider Harness			<u> </u>	I ology Perfo	rmed? No		Se	I econd Pilot? No		
	1											
Flight Plan/Itinerary												
Type of Flight Plan Filed: IFI	 R											
Departure Point					State	State Airpo		Airport Identifier		rture Time	Time Zone	
Same as Accident/Incide	nt Location							LEW			EST	
Destination					State	e Ai	Airport Identifier			,		
Manchester	NH											
Type of Clearance: IFR												
Type of Airspace: Unknow	wn											
Weather Information												
Source of Briefing: Unknown												
Method of Briefing: Unknown												
	FACTUAL REPORT - AVIATION Page 3											

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: IAD02LA021

Occurrence Date: 12/20/2001

Occurrence Type: Accident

	FIYBOR		Occurrenc	,е туре.	Acciden	<u>، د</u>							
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Distance From Accident Site					Direction From Accident Site			
LEW	2055	EST	288 Ft.	MSL				0 NM		Deg. Mag.			
Sky/Lowes	st Cloud Condition:				•	Ft. A	.GL	Condition o	of Ligh	nt: Night/Dark			
Lowest Ce	eiling: Broken	100 Ft.	AGL	Visibi	ility:	1.75	SM	Altimeter: 29.54		"Hg			
Temperatu	-1 °C	Wind	d Direction: 360 Density Altitude:							Ft.			
Wind Spee	∍d: 4	Gusts:		Weather Conditions at Accident Site: Instrument Conditions									
Visibility (F	RVR): Ft.	Visibility (RV	/V)	SM	Intensity	y of Precipi	itation:	Moderate					
Restriction	ns to Visibility: None												
Type of Precipitation: Snow													
Accident	Information												
Aircraft Da	mage:		Aircraft Fire	Aircraft Fire:					Aircraft Explosion				
Classificati	on:												
- Injury Su	mmary Matrix	Fatal Ser	rious Mino	or	None	TOTAL							
First Pi	ilot				1	1	1						
Second	d Pilot]						
Studen	nt Pilot						7						
Flight I	nstructor						7						
Check	Pilot			\top			1						
Flight E	Engineer						7						
Cabin A	Attendants						7						
Other 0	Crew						7						
Passer	ngers						7						
- TOTAL A	ABOARD -				1		1						
Other C	Ground				-		7						
- GRANE	O TOTAL -				1		1						
		·											

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: IAD02LA021

Occurrence Date: 12/20/2001

Occurrence Type: Accident

Αc	lm	inis	trati	ve	Ini	fori	mati	ion

Investigator-In-Charge (IIC)

Brian C. Rayner

Additional Persons Participating in This Accident/Incident Investigation:

James Edwards FAA District Office/Coordinator Portland, ME